# **Depository Access - Operator Training**

- Starting procedure for the propane loading department;
- Starting procedure for mix loading/unloading;

# Personal Protective Equipment (P.P.E.) required for accessing and remaining in the depository

P.P.E.	PICTOGRAMS OF THE FEATURES
Safety Helmet	
Safety Goggles	
Gloves	
Footwear	CE F
Coverall	MCE E

- Access without wearing P.P.E.
- Use electric or electronic equipment without the atex label having this symbol:



## Avvio al Carico o Scarico per chiamata:

4

1) Swiss-phone pager

What is given to the operator after checking in:

2) Loading Electronic badge



Contains all the loading information.


Type of product and net weight: To

be delivered to the terminal staff

Notifies when to enter
Gate and terminal number:
To silence it, press the blue button
3 times




#### HOW TO FIND YOUR WAY AROUND



### Propane loading path



# Mix loading and unloading path



#### **Penalties:**

	8 Type of violation	Penalty provided:		
		1° time	2° time	3° time
	Not using the required P.P.E.	Oral reprimand, noted in the sanction register	Written reprimand addressed to the transport company	One month suspension
	Not respecting the loading and unloading procedures	Oral reprimand, noted in the sanction register	Written reprimand addressed to the transport company	One month suspension
	Using your phone in the terminal	Oral reprimand, noted in the sanction register	Written reprimand addressed to the transport company	One month suspension
	Using Webasto burner in the terminal or any other device non ATEX compliant	Written reprimand to the transport company, noted in the register	One month suspension	Indefinite suspension
	$\langle \epsilon_x \rangle$			

# IN THE RESTING AREA, THE VEHICLE MUST BE ATTACHED TO A TRACTOR AND WITH AN OPERATOR







